



apollo

by Sheridan
stainless steel sinks

Apollo® stainless steel sinks

- High grade 18/08 Stainless Steel brush satin finish
- Impact resistant
- Complement any decor
- Resistant to mould, bacteria and mildew
- Extremely hard wearing - scratch and heat resistant
- Easy to clean and maintain
- Has more overall usable space than porcelain or cast iron
- Anti condensation - full gypsum coating and silencer pad on Avignon and Auxerre sinks

See our website www.sheridan-uk.com for further information on this and other apollo® products.

apollo® stainless steel sinks			
Cat No.	Description	Sizes (L x W x D)	Price
AVIGNON APUM4634†	Undermounted 1 1/2 Bowl LH left /RH right hand small bowl*	180 x 360 x 130mm 346 x 460 x 200mm	📞
AUXERRE APUM5540†	Undermounted 1 1/2 Bowl LH left /RH right hand small bowl*	150 x 400 x 130mm 330 x 400 x 185mm	📞
BIARRITZ APUM9948	Inset 1 1/2 Bowl Universal drainer	175 x 299 x 110mm 340 x 400 x 180mm	📞
Other Items			
We recommend Rotabond 2000 Silicone Sealant when undermounting or sealing sinks, see website: www.kenteurope.com/uk for details			

Please note:

† includes a basket strainer waste

* Please specify left or right handed

FRANKE undermounted stainless steel sinks			
Cat No.	Description	Sizes (L x W x D)	Price
ARX 110 17†	Half Bowl	170 x 320 x 130mm	📞
ARX110 33†	Single Bowl	330 x 350 x 160mm	📞
ARX 110 35†	Single Bowl	350 x 435 x 180mm	📞
ARX 160†*	Double Bowl	350 x 435 x 195 /170 x 320 x 150mm	📞
KBX 110 45†	Single Bowl	450 x 400 x 180mm	📞
LAX 110 50†	Single Bowl	500 x 350 x 195mm	📞

Please note:

† includes a full plumbing kit, basket strainer waste

* Please specify left or right handed

Other sinks are available, please contact our sales department for further information.

Fitting sinks

Fitting Stainless Steel Sink (bespoke worktops)

Apollo® undermounted stainless steel sinks



Apollo® Avignon



Apollo® Auxerre

Apollo® inset stainless steel sinks



Apollo® Biarritz

WARRANTY

All our products carry a 10 Year Manufacturer's Limited Warranty!



Please Note

Silicone sealant may be rendered ineffective when connecting taps and plumbing in the sink. It is important that the sink is re-sealed immediately after connection to avoid moisture ingress, failure to do so will invalidate the warranty.